

- **FRAME—“POPPING/CREAKING”—FASTENER REPLACEMENT**
- **NOISE—“POPPING/CREAKING”—FRONT FRAME OR SUSPENSION BRACKETS**

**Article No.
97-3-10**

FORD: 1980-1996 BRONCO, F-150, F-250 LD
1980-1997 F-250 HD, F-350
1988-1997 F SUPER DUTY, F-47

This TSB article is being republished in its entirety to include vehicles built through the 1997 model year and to update the Transmission Crossmember Service Procedure.

ISSUE

A “popping/creaking” sound may come from the area of the front frame or suspension brackets. This may occur because of a slip/stick motion at a loose rivet or bolt in a frame crossmember or a suspension bracket (radius arm, spring tower, spring shackle, etc.).

ACTION

Use the following Diagnostic Procedure to determine the location of the noise. Replace the suspected fastener(s) by referring to the following Repair Procedure for details.

SOURCES OF VARIOUS FRONT UNDERBODY NOISES

Various front underbody noises may originate from several different sources and are often difficult to locate and diagnose. Common noise locations include:

- #1 (engine) crossmember rivets - primarily the rivet or “huck fastener” at the lower left front, behind the steering gear
- loose or improperly seated spring shock tower rivets/bolts
- loose or misaligned transmission crossmembers
- loose or improperly seated front leaf spring bracket rivets
- loose radius arm brackets
- loose axle pivot brackets

Other underbody areas that produce similar noises include:

- transfer case skid plate
- leaf spring bushings
- steering intermediate shafts
- shock bolts
- bumper brackets
- brakes

Other Service Bulletins have been published to address the proper repair of these concerns.

DIAGNOSTIC PROCEDURE

1. INTERVIEW THE CUSTOMER
 - a. Understand the customer's description of the noise and of the conditions under which it is heard.
 - b. Road test the vehicle with the customer to fully understand where, how, and when the noise occurs.
2. DUPLICATE THE NOISE CONCERN
 - a. Drive the vehicle around for at least 15 minutes to warm-up and exercise the frame joints so that any frame noise is more likely to be repeatable in the garage or on the road.
 - b. Identify the conditions in which the noise is repeatable. Does the noise occur:
 - While parked and turning the wheels lock-to-lock?
 - Only when driving?
 - While going straight over bumps?
 - While on a lift with the suspension unloaded?
 - Only when the brakes are applied?

Article No. 97-3-10 Cont'd.

- c. Identify the general location of the noise.
Can you "feel" the noise in the floorboard or the steering wheel? Refer to Figure 9 for likely locations for the noise.

NOTE

USE CHASSIS EARS AND/OR A STETHOSCOPE TO DETERMINE THE LOUDEST POINT OF THE NOISE. IF THE NOISE IS REPRODUCIBLE WHEN STATIONARY, PUT THE VEHICLE ON A DRIVE-ON LIFT AND "FEEL" FOR ANY MOVEMENT OR VIBRATION AT THE JOINTS.

3. INSPECT FRAME BOLTS FOR PROPER INSTALLATION TORQUE

Inspect and tighten all front end components which bolt to the frame to confirm that they are at the proper torque (refer to the Repair Procedure section of this article for proper torque requirements). This includes, but is not limited to:

- radius arm bracket bolts
- axle pivot bracket bolts
- transmission crossmember bolts
- spring tower bolts

4. INSPECT THE FRAME RIVETS

- Inspect all riveted frame and suspension components in the general area of the noise for loose or improperly seated rivets.

NOTE

TAP THE RIVETS WITH A SMALL HAMMER. WHEN A RIVET IS NOT INSTALLED PROPERLY IT WILL MAKE A DIFFERENT SOUND THAN A "SNUG" RIVET.

- Service identified rivets according to the procedure listed in the Repair Procedure section.

5. TEST DRIVE THE VEHICLE

Road test the vehicle again to duplicate the concern. If the noise is still present, proceed to the next Step.

6. TEST JOINTS TO LOCATE NOISE

- Use a small pry bar as a "wedge" between components suspected of causing the noise. By pounding the wedge into a joint or behind a bracket, the noise should change or be eliminated if the noise is coming from that location.

NOTE

USING A STETHOSCOPE, OR CHASSIS EARS, WILL HELP TO IDENTIFY ANY NOISE CHANGE.

- If the source of the noise is identified, proceed to the Repair Procedure section.
- If the source of the noise has not been identified by this Step, investigate other non-frame or suspension sources and/or proceed to the next Step.

7. SERVICE THE VEHICLE

- a. If the noise has been identified, proceed to the specific component section in the Repair Procedure.
- b. If the noise source has not been identified, refer to Figure 9 for general noise locations, operating conditions and number of occurrences. Proceed with repairing the identified components.

REPAIR PROCEDURE - (A) THROUGH (H)

(A) "Huck Fastener" - Lower Left Front #1 Crossmember Rivet Replacement

This procedure should be done on flat ground or on a drive-on lift, with the wheels pointed straight and full weight resting on the wheels. This fastener could be either a standard cold head rivet in light duty applications or a large "huck" bolt which has the appearance of a large "pop" rivet.

NOTE

USE WARRANTY DEALER CODING: 5020, AS BASIC PART NO.

1. Remove damaged or loose rivet:

COLD HEAD RIVETS:

- Drill a 3.175mm (1/8") hole through the rivet.
- Redrill the same hole through the shank of the rivet with a 9.525mm (3/8") drill.
- Remove the rivet head with an air chisel.
- Drive out the rivet with a punch and hammer.

"HUCK" RIVETS:

- Use a flat chisel and hammer (or air chisel) to split the exposed collar of the huck fastener (Figure 1).
- Knock the rivet pin out of the blind side with a 6.35mm (1/4") drift punch and hammer (Figure 2).
- Cut the rivet's head off with a hammer and flat chisel (Figure 3).
- Knock the sleeve out of the blind side with a 9.525mm (3/8") drift punch and hammer (Figure 4).

CAUTION

DO NOT REMOVE THE FASTENER WITH A CUTTING TORCH BECAUSE DAMAGE TO THE FRAME STRUCTURE IS LIKELY TO RESULT.

2. After removing the rivet, verify the noise came from this location by pounding a wedge between the crossmember and the frame liner, then driving the vehicle to reproduce the noise. The wedge will lift the crossmember off of the inner frame liner and eliminate any noise if the lower left front #1 crossmember joint is the source of the noise.
3. With the wedge still in place, insert the Bearing Strip (F6TZ-5D033-BA) between the #1 crossmember and frame liner. Align the strip approximately centered and extending well past the hole location. Remove the wedge and drill a 11.113mm (7/16") diameter hole through the bearing strip.
4. Line ream the existing hole through the liner, frame flange and crossmember to 14.288mm (9/16") (Figure 5). Remove any burrs after reaming.

NOTE

TO PROPERLY REAM THE HOLE ON A VEHICLE WITH LEAF SPRINGS, THE SPRING MUST BE REMOVED TO PROVIDE VERTICAL ACCESS TO THE RIVET HOLE.

5. Install a 9/16" Grade 8 torque prevailing Nut (34990-S2) with a Washer (44880-S2) and a Grade 8 Bolt (58698-S2) with a Washer (44880-S2) (Figure 6).
 - a. Slide the bolt and washer into the "window" opening on the outside of the frame siderail, and insert it into the newly-reamed hole.

NOTE

ON VEHICLES WITH QUAD SHOCK ABSORBERS, IT MAY BE NECESSARY TO REMOVE THE SHOCK/SPRING TOWER TO GAIN ACCESS TO THE "WINDOW" IN THE SIDERAIL.

- b. Install the washer and nut and torque nut to $190 \pm 4 \text{ N}\cdot\text{m}$ ($140 \pm 3 \text{ lb}\cdot\text{ft}$). Turn the wheels lock-to-lock several times to seat the joint and retorque. Tack weld the nut to the bolt after tightening.

CAUTION

DO NOT WELD THE NUT/WASHER TO THE FRAME.

NOTE

ON HEAVY DUTY VEHICLES, IT MAY BE NECESSARY TO UPGRADE THE REPLACEMENT FASTENER TO A 5/8" GRADE 8 TORQUE PREVAILING NUT (34991-S2), BOLT (58720-S100) AND TWO (2) WASHERS (44881-S2) TORQUED TO $250 \pm 6.8 \text{ N}\cdot\text{m}$ ($185 \pm 5 \text{ LB}\cdot\text{FT}$).

(B) Other #1 Crossmember Rivets

NOTE

USE WARRANTY DEALER CODING: 5020, AS BASIC PART NO.

Follow the "Huck Fastener"/Repair Procedure A, listed in this article for cold head rivets and replace the rivet with a 9/16" Grade 8 torque prevailing Nut (34990-S2) with a Washer (44880-S2) and a Grade 8 Bolt (58698-S2) with a Washer (44880-S2).

(C) Other Rivets

NOTE

USE WARRANTY DEALER CODING: 5004, AS BASIC PART NO.

Follow TSB 96-15-11 for proper rivet replacement procedure.

(D) Transmission Crossmember

NOTE

USE WARRANTY DEALER CODING: 5060, AS BASIC PART NO.

This procedure should be done on flat ground or on a drive-on lift, with the wheels pointed straight and full weight resting on the wheels.

NOTE

A SIMILAR NOISE CAN OCCUR AT THE TRANSFER CASE SKID PLATE ATTACHMENTS AND SHOULD BE INVESTIGATED IN

Article No. 97-3-10 Cont'd.

CONJUNCTION WITH THIS REPAIR PROCEDURE.

1. Remove transmission weight:
 - a. Remove bolts attaching transmission mount to the crossmember.
 - b. Lift the transmission to remove any load to the crossmember. The crossmember should now be completely loose.

NOTE

YOU MAY NOTICE THE FRAME RAILS TWIST SLIGHTLY AND "RELAX" AFTER THIS NEXT STEP.

2. Loosen crossmember:
 - a. Loosen all bolts attaching the crossmember to the frame siderails.
 - b. Loosen all bolts attaching the crossmember gusset(s) to the crossmember and to the frame siderails. The crossmember should now be completely loose.
3. Turn the steering wheel lock-to-lock and then straighten the wheels. This helps to remove any stress in the frame.
4. Install new crossmember fastening hardware one at a time and replace each nut and bolt with a new Nut (N800937-S427) and Bolt (N802114-S2) and leave them loosely assembled until all crossmember and gusset fasteners have been replaced.

NOTE

IT IS IMPERATIVE THAT THE FOLLOWING TIGHTENING SEQUENCE BE FOLLOWED.

5. Secure the crossmember attaching hardware. Determine which style of crossmember the vehicle is equipped with, and follow Step 6 or 7.
6. If the vehicle has a wraparound-style crossmember (Figure 7), torque each grouping of fasteners in the order listed in the following Substeps to $70 \pm 10.5 \text{ N}\cdot\text{m}$ ($52 \pm 8 \text{ lb}\cdot\text{ft}$).
 - a. Torque all three (3) bolts/nuts at the crossmember-to-frame siderail at the wraparound side (Figure 7, Number 1).
 - b. Torque the gusset-to-frame bolts (Figure 7, Number 2).

- c. Torque the crossmember-to-frame bolts (Figure 7, Number 3).
- d. Torque the gusset-to-crossmember bolts (Figure 7, Number 4).
7. If the vehicle has a double-gusseted crossmember (Figure 8), torque each grouping of fasteners in the order listed in the following Substeps to $70 \pm 10.5 \text{ N}\cdot\text{m}$ ($52 \pm 8 \text{ lb}\cdot\text{ft}$) and repeat for the other side.
 - a. Torque the gusset-to-frame bolts (Figure 8, Number 1).
 - b. Torque the crossmember-to-frame bolts (Figure 8, Number 2).
 - c. Torque the gusset-to-crossmember bolts (Figure 8, Number 3).
8. Reattach transmission:
 - a. Lower the transmission.
 - b. Reattach the transmission using new Nuts (N621945-S2) and torque to $95 \pm 15 \text{ N}\cdot\text{m}$ ($70 \pm 11 \text{ lb}\cdot\text{ft}$).
9. Inspect gusset/crossmember joint:
 - a. Visually inspect the joint between the gusset and crossmember. If all fasteners have been torqued properly and any gap exists between the two, shim joint with washers.
 - b. Reattach the gusset with new Bolts (N802114-S2) and Nuts (N800937-S427) torqued to $70 \pm 10.5 \text{ N}\cdot\text{m}$ ($52 \pm 7 \text{ lb}\cdot\text{ft}$).

NOTE

ON HEAVY DUTY VEHICLES, IT MAY BE NECESSARY TO UPGRADE THE REPLACEMENT FASTENER TO A 9/16" GRADE 8 TORQUE PREVAILING NUT (34990-S2) AND BOLT (58698-S2) TORQUED TO $190 \pm 4 \text{ N}\cdot\text{m}$ ($140 \pm 3 \text{ LB}\cdot\text{FT}$).

(E) Radius Arm Brackets

NOTE

USE WARRANTY DEALER CODING: 3B095, AS BASIC PART NO.

1. Inspect and retorque all radius arm bracket bolt(s) to $135 \pm 20 \text{ N}\cdot\text{m}$ ($100 \pm 15 \text{ lb}\cdot\text{ft}$).

NOTE

IF THE BOLT IS VERY LOOSE AND THE BRACKET IS NOT CLAMPED TIGHTLY, INSPECT

THE FRAME AND BRACKET HOLES FOR ELONGATION. IF A BRACKET HOLE IS ELONGATED, THE BRACKET MUST BE REPLACED. IF A FRAME HOLE IS ELONGATED, THE ENTIRE FRAME MUST BE REPLACED, OR THE FRAME AND BRACKET HOLES MUST BE DRILLED OUT TO A LARGER SIZE, NOT TO EXCEED 15mm (19/32"), AND A LARGER NUT AND BOLT MUST BE INSTALLED.

2. Inspect the rivets for looseness. Replace any loose or poorly seated rivets using the following procedure:

NOTE

MOST OFTEN, THE NOISE CAN BE ELIMINATED BY REPLACING ONLY THE MIDDLE RIVET OF THE THREE (3) SECURING THE BRACKET.

- a. Remove damaged or loose rivet:
 - Drill a 3.175mm (1/8") hole through the rivet.
 - Redrill the same hole through the shank of the rivet with a 9.525mm (3/8") drill.
 - Remove the rivet head with an air chisel.
 - Drive out the rivet with a punch and hammer.

CAUTION

DO NOT REMOVE THE FASTENER WITH A CUTTING TORCH BECAUSE DAMAGE TO THE FRAME STRUCTURE IS LIKELY TO RESULT.

- b. Line ream the hole to the replacement bolt size of 12.7mm (1/2").
- c. Clean hole of burrs after reaming so that the bolt head and nut will seat properly.
- d. Install a new Bolt (N802210-S2) and Nut (N800937-S427), and torque to 133 ±20 N•m (98 ±15 lb-ft).

(F) Spring Towers

NOTE

USE WARRANTY DEALER CODING: 5A306, AS BASIC PART NO.

Inspect the rivets for looseness. Replace any loose or poorly seated rivets using the following procedure.

1. Remove damaged or loose rivet:
 - a. Drill a 3.175mm (1/8") hole through the rivet.

- b. Redrill the same hole through the shank of the rivet with a 9.525mm (3/8") drill.
- c. Remove the rivet head with an air chisel.
- d. Drive out the rivet with a punch and hammer.

CAUTION

DO NOT REMOVE THE FASTENER WITH A CUTTING TORCH BECAUSE DAMAGE TO THE FRAME STRUCTURE IS LIKELY TO RESULT.

2. Line ream the hole to the replacement bolt size of 11.113mm (7/16").
3. Clean hole of burrs after reaming so that the bolt head and nut will seat properly.
4. Install a new Bolt (56561-S2) and Nut (382400-S2), and torque to 89 ±13 N•m (66 ±10 lb-ft).

(G) Front Leaf Spring Brackets

NOTE

USE WARRANTY DEALER CODING: 5340, AS BASIC PART NO.

Inspect the rivets for looseness. Replace any loose or poorly seated rivets using the following procedure.

1. Remove damaged or loose rivet:
 - a. Drill a 3.175mm (1/8") hole through the rivet.
 - b. Redrill the same hole through the shank of the rivet with a 8.731mm (11/32") drill.
 - c. Remove the rivet head with an air chisel.
 - d. Drive out the rivet with a punch and hammer.

CAUTION

DO NOT REMOVE THE FASTENER WITH A CUTTING TORCH BECAUSE DAMAGE TO THE FRAME STRUCTURE IS LIKELY TO RESULT.

2. Install a new Bolt (58634-S2), two (2) Washers (44877-S2) and a Nut (34987-S2). Torque to 62 ±15 N•m (46 ±11 lb-ft).

(H) Axle Pivot Brackets

NOTE

USE WARRANTY DEALER CODING: 3B178, AS BASIC PART NO.

Article No. 97-3-10 Cont'd.

Inspect and retorque all axle pivot bracket bolts (torque values may vary by model - refer to the appropriate light truck Service Manual for proper torque specifications).

NOTE

IF THE BOLT IS LOOSE AND THE BRACKET IS NOT CLAMPED TIGHTLY, INSPECT THE FRAME AND BRACKET HOLES FOR ELONGATION. IF A FRAME HOLE IS ELONGATED, THE ENTIRE FRAME MUST BE REPLACED. NO FRAME REPAIRS ARE AUTHORIZED ON THESE #1 CROSSMEMBER HOLES.

PART NUMBER	PART NAME
34990-S2	Grade 8 Torque Prevailing Nut - 9/16"
44880-S2	Washer - 9/16" (Pk/12)
58698-S2	Grade 8 Bolt - 9/16"-12x1.75 (Pk/4)
34991-S2	Grade 8 Torque Prevailing Nut - 5/8"
44881-S2	Washer - 5/8" (Pk/12)
58720-S100	Grade 8 Bolt - 5/8" (Pk/4)
N802114-S2	Bolt
N800937-S427	Nut
N621945-S2	Nut
N802210-S2	Bolt
56561-S2	Bolt
382400-S2	Nut
58634-S2	Bolt
44877-S2	Washer
34987-S2	Nut
F6TZ-5D033-BA	Low Friction Insert

OTHER APPLICABLE ARTICLES: 96-15-11

SUPERSEDES: 96-4-11

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage For 1992-96 Model Years, Basic Warranty Coverage For All Others

OPERATION	DESCRIPTION	TIME
970310A	Perform Diagnostics - Includes Road Test	0.7 Hr.
970310B	"Huck Fastener" - Replace (Repair A) - Includes Additional Road Test And Transmission Crossmember Repair (Repair D) - Not To Be Used With Operation D	1.1 Hr.
970310CA	#1 Crossmember And Other Rivets - Replace Two (Repairs B And C)	0.9 Hr.
970310CB	#1 Crossmember And Other Rivets - Replace Three (Repairs B And C)	1.3 Hrs.

970310CC	#1 Crossmember And Other Rivets - Replace Four (Repairs B And C)	1.7 Hrs.
970310CT	#1 Crossmember And Other Rivets - Replace Five Or More (Repairs B And C)	2.1 Hrs.
970310C	#1 Crossmember And Other Rivets - Replace One (Repairs B And C)	0.5 Hr.
970310D	Transmission Crossmember (Repair D) - Not To Be Used With Operation B	0.5 Hr.
970310E	Radius Arm Bracket (Repair E) - Inspect And Check Fastener Torque	0.2 Hr.
970310FT	Radius Arm Bracket - Replace Both (Repair E) - Not To Be Used With Operations G And GT	1.3 Hrs.
970310F	Radius Arm Bracket - Replace One (Repair E) - Not To Be Used With Operations G And GT	0.7 Hr.
970310GT	Radius Arm Bracket Rivet - Replace Both (Repair E) - Not To Be Used With Operations F And FT	0.9 Hr.
970310G	Radius Arm Bracket Rivet - Replace One (Repair E) - Not To Be Used With Operations F And FT	0.5 Hr.
970310HA	Spring Tower Rivet - Replace Two (Repair F)	1.0 Hr.
970310HB	Spring Tower Rivet - Replace Three (Repair F)	1.4 Hrs.
970310HC	Spring Tower Rivet - Replace Four (Repair F)	1.8 Hrs.
970310HT	Spring Tower Rivet - Replace Five Or More (Repair F)	2.2 Hrs.
970310H	Spring Tower Rivet - Replace One (Repair F)	0.6 Hr.
970310IA	Front Leaf Spring Bracket Rivet - Replace Two (Repair G)	0.9 Hr.
970310IB	Front Leaf Spring Bracket Rivet - Replace Three (Repair G)	1.3 Hrs.
970310IC	Front Leaf Spring Bracket Rivet - Replace Four (Repair G)	1.7 Hrs.

970310IT	Front Leaf Spring Bracket	2.1 Hrs.
	Rivet - Replace Five Or More (Repair G)	
970310I	Front Leaf Spring Bracket	0.5 Hr.
	Rivet - Replace One (Repair G)	
970310J	Axle Pivot Bracket -	0.2 Hr.
	Inspect And Check Fastener Torque	

DEALER CODING

BASIC PART NO.	CONDITION CODE
3B095 FOR REPAIR PROCEDURE E	56
3B178 FOR REPAIR PROCEDURE H	56
5004 FOR REPAIR PROCEDURE C	56
5020 FOR REPAIR PROCEDURE A	56
5020 FOR REPAIR PROCEDURE B	56
5060 FOR REPAIR PROCEDURE D	56
5340 FOR REPAIR PROCEDURE G	56
5A306 FOR REPAIR PROCEDURE F	56

OASIS CODES: 305000, 390000, 702000, 702100




Figure 1 - Article 97-3-10




Figure 2 - Article 97-3-10




Figure 3 - Article 97-3-10




Figure 4 - Article 97-3-10




Figure 5 - Article 97-3-10




Figure 6 - Article 97-3-10




Figure 7 - Article 97-3-10




Figure 8 - Article 97-3-10

COMPONENT	NOISE LOCATION			OPERATING CONDITIONS						NO. OF "POPS"	
	Left Front	Right Front	Midship	Stationary Lock-to-Lock	Driving Straight Over Bumps	With Suspension Unloaded	Brakes Not Applied	"Feel" Noise in Floor Boards	Multiple "Pops" (i.e., Ratchet)	Single Pop/Creak	
Huck Fastener	X			X		X	X		(X)	X	
Other #1 C/M Fastener	X	X		X		X	X		(X)	X	
Transmission C/M			X	X		X	X	(X)	(X)	X	
Radius Arm Bracket			X	X	(X)	(X)	(X)	X	X	(X)	
Spring Tower	X	X		X	(X)		(X)		(X)	X	
Front Left Spring Bracket	X	X	X	X	X	(X)	(X)	(X)	(X)	X	
Axle Pivot Bracket	X	X		(X)	(X)		(X)		(X)	(X)	
Other Suspension	X	X	X	(X)	(X)		(X)		(X)	(X)	

X = MOST OFTEN (X) = SOMETIMES

TB-4209-A

Figure 9 - Article 97-3-10