

## Detailed Vehicle Specification

VIN					
Vehicle Line	T/F7	Market Derived Code	F		
Body Cab	T/BD	Ver. Series	T/BD		
Drive Type	T/E				
PLT CD	A1	TRS CD	T/BE	ENG CD	T/QL
Production Date	13-NOV-08	Warranty Start Date	30-JUN-09		
Selling Dealer	147059	Selling Country	USA		

AWS Claim Key	Trx Code	Time In Service	Labor Hours	Dealership	DIST (Miles)	Repair Date	Prefix	Base	Suffix	Doc
Details	1704473	E83	13	4	MIKE RAISOR FORD	30693	20-JUL-10	9C3Z	19E616 B	06913851
		<b>Customer Comments</b>	CUSTOMER STATES THE TEMPS WILL VARY GREATLY BETWEEN EACH SIDE ON THE CLIMATE CONTROL. ONE SIDE WILL BE HOT AND ONE SIDE WILL BE COLD.							
		<b>Tech Comments</b>	REPLACE THE RIGHT AND LEFT ACTUATOR MOTOR ASSEMBLIES PER TSB 091215 ***SERVICE DIRECTOR HAS REVIEWED AND APPROVED CLAIM***							
Details	2442707	E95	21	1.4	MIKE RAISOR FORD	47179	04-MAR-11	BL3Z	4676 A	08786251
		<b>Customer Comments</b>	CUSTOMER STATES: REPAIR LEAK AT REAR END							
		<b>Tech Comments</b>	DIAG, FOUND LEAK AT REAR PINION SEAL . REPLACE PINION SEAL . RETEST O.K.							
Details	2570459	11B24	22	.4	MIKE RAISOR FORD	48009	15-APR-11	*	*	09147341
		<b>Customer Comments</b>	11B24 CONTINENTAL TIRE INSPECTION							
		<b>Tech Comments</b>	CHECK TIRES . DATE CODES NOT INVOLVED IN RECALL							
Details	2570458	11B23	22	.5	MIKE RAISOR FORD	48009	15-APR-11	*	*	09147340
		<b>Customer Comments</b>	11B23 POWERTRAIN CONTROL MODULE RECALIBRATION							
		<b>Tech Comments</b>	UPDATE PCM							
Details	3405750	E72	29	1.6	MIKE RAISOR FORD	56004	02-NOV-11	7C3Z	6B209 D	00876651
		<b>Customer Comments</b>	CUSTOMER STATES CHIRPING NOISE COMING FROM UNDER THE HOOD							
		<b>Tech Comments</b>	DIAG.FOUND TENSIONER WEAK AND PULLEY NOISEY. REPLACE TENSIONER & PULLEY. NOISE GONE NOW.							